

JOHN A. SANCHEZ Lieutenant Governor

NEW MEXICO ENVIRONMENT DEPARTMENT

Surface Water Quality Bureau

Harold Runnels Building, N2050 1190 South St. Francis Drive (87505) P.O. Box 5469, Santa Fe, NM 87502-5469 Phone (505) 827-0187 Fax (505) 827-0160 www.nmenv.state.nm.us



BUTCH TONGATE Deputy Secretary

ERIKA SCHWENDER Director

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

August 15, 2013

Ms. Debi Lee, Village Manager Village of Ruidoso 313 Cree Meadows Dr. Ruidoso, NM 88345 Mr. Cleatus Richards, Utilities Director City of Ruidoso Downs P.O. Box 348 Ruidoso Downs, NM 88346

Re: Major Municipal, SIC 4952, NPDES Compliance Evaluation Inspection, Ruidoso/Ruidoso Downs WWTP, NM0029165, July 22, 2013

Dear Ms. Lee and Mr. Richards,

Enclosed, please find a copy of the report and checklist for the referenced inspection that the New Mexico Environment Department (NMED) conducted at your facility on behalf of the U.S. Environmental Protection Agency (USEPA). This inspection report will be sent to the USEPA in Dallas for their review. These inspections are used by USEPA to determine compliance with the National Pollutant Discharge Elimination System (NPDES) permitting program in accordance with requirements of the Federal Clean Water Act.

Findings are based on the inspector's observances in regards to specific requirements of the NPDES permit. The Ruidoso WWTP received an overall evaluation rating of "4" on a scale of 1 to 5. The evaluation indicates the quality of the self-monitoring program for a specific facility. The highest rating of "5" is used for facilities with very reliable self-monitoring programs, a "3" is considered satisfactory, and a "1" is used for very unreliable self-monitoring programs.

The main issue was found relating to Laboratory Procedures. Please refer to the Further Explanations section of the report for more detail.

I wish to thank you for the cooperation extended to the NMED while at the Ruidoso Wastewater Treatment Plant by Bobby Snowden and Isaac Garcia. If you have any questions about this inspection report, please contact me at (505) 222-9587 or sarah.holcomb@state.nm.us.

Sincerely,
/s/ Sarah Holcomb
Sarah Holcomb
Environmental Scientist/Specialist
Surface Water Quality Bureau

Cc: Carol Peters-Wagnon, USEPA (6EN-WM) by email Hannah Branning, USEPA (6EN-AS), by email Samuel Tates, USEPA (6EN-AS) by email Rashida Bowlin, USEPA (6EN-AS) by email Larry Giglio, USEPA (6WQ-P) by email Diana McDonald, USEPA (6EN-WM) by email Frank Fiore, NMED District III Manager, by email

Form Approved OMB No. 2040-0003 Approval Expires 7-31-85



NPDES Compliance Inspection Report

Section A: National Data System Coding																							
Transaction Code NPDES 1 N 2 5 3 N M 0 0 2 9 1				6	5	11	12	1	3	0 yr	/mo/d	ау 2	5	17	Ins	pec. T	ype	Ir 19	spect S	or 20	Fac Type		
	M A J O R	w	w T	P					Remar	ks													Ш
Inspection Work Days Facility Evaluation Ra					ating		71	BI N	72	QA				 	Reserved								
N	Section B: Facility Data Name and I section of Earlike Learnested (Facility Installation of Earlike Learnested (Facility Data) Page 15 February 15 F																						
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) RUIDOSO DOWNS WWTP, LINCOLN COUNTY, NEW MEXICO; DRIVE THROUGH RUIDOSO, TURN EAST ON NM70. TRAVEL THROUGH RUIDOSO DOWNS; FACILITY IS								e Dat	e 														
	DOSO, TOKN EAST ON NM70. TRA 26675 US 70.	VEL	THROU	OH KC	шоз	ОВО	wns,	FAC	ILIII	13		it Time 15 HO			2012				nit Ex 1-2017		on Da	ite	
MR.	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) MR. BOBBY SNOWDEN, DEPARTMENT MANAGER (575) 378-8417 MR. ISAAC GARCIA, CHIEF OPERATOR GPS:																						
Name, Address of Responsible Official/Title/Phone and Fax Number MS. DEBI LEE, VILLAGE MANAGER, VILLAGE OF RUIDOSO 313 CREE MEADOWS DR, RUIDOSO, NM 88345 MR. CLEATUS RICHARDS, UTILITIES DIRECTOR, CITY OF RUIDOSO DOWNS PO BOX 348, RUIDOSO DOWNS, NM 88346 W. 33° 21' 38" W105° 32' 36" SIC: 4952																							
	Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)																						
S	Permit	S	Flow N	Aeasur	emen	t			S	Op	eratio	ns & N	Mainte	enance	e		N	CSO	/SSO				
M	Records/Reports	S	Self-N	Ionito	ring P	rograi	gram S Sludge Handling/Disposal N Pollution Preven			ntion													
S	Facility Site Review	N	Comp	liance	Sched	lules			N	1 Tetreatment			Mult	imedi	a								
S Effluent/Receiving Waters M Laboratory					N Storm Water N Other:						r:												
Section D: Summary of Findings/Comments (Attach additional sheets if necessary) 1. INSPECTORS ARRIVED AT THE FACILITY AT 1100 HOURS ON JUNE 25, 2013 AND CONDUCTED ENTRANCE INTERVIEW WITH MR. BOBBY SNOWDEN AND MR. ISAAC GARCIA. THE INSPECTOR MADE INTRODUCTIONS, PRESENTED HER CREDENTIALS AND DISCUSSED THE PURPOSE OF THE INSPECTION. 2. PLEASE SEE INSPECTION REPORT FOR FURTHER DETAILS.																							
Name(s) and Signature(s) of Inspector(s)					Agency/Office/Telephone/Fax							Date											
Sarah Holcomb /s/ Sarah Holcomb						505-	222-9	587										8-15-2013					
Signature of Management QA Reviewer					Agency/Office/Phone and Fax Numbers						Date												
Bruce Yurdin /s/ Bruce Yurdin					505-827-2798							8-14-2013											

RUIDOSO/RUIDOSO DOWNS WWTP	
	PERMIT NO. NM0029165
SECTION A - PERMIT VERIFICATION	
PERMIT SATISFACTORILY ADDRESSES OBSERVATIONS DETAILS: □ NA (FURTHER EXPERIMENTS)	KPLANATION ATTACHED <u>NO</u>)
1. CORRECT NAME AND MAILING ADDRESS OF PERMITTEE	\boxtimes Y \square N \square NA
2. NOTIFICATION GIVEN TO EPA/STATE OF NEW DIFFERENT OR INCREASED DISCHARGES	□Y□N ⊠NA
3. NUMBER AND LOCATION OF DISCHARGE POINTS AS DESCRIBED IN PERMIT	⊠Y□N □NA
4. ALL DISCHARGES ARE PERMITTED	⊠Y□N □NA
SECTION B - RECORDKEEPING AND REPORTING EVALUATION	
RECORDS AND REPORTS MAINTAINED AS REQUIRED BY PERMIT. S	ER EXPLANATION ATTACHED <u>NO</u>)
1. ANALYTICAL RESULTS CONSISTENT WITH DATA REPORTED ON DMRs.	⊠Y □ N □ NA
2. SAMPLING AND ANALYSES DATA ADEQUATE AND INCLUDE.	⊠S □M □U □NA
a) DATES, TIME(S) AND LOCATION(S) OF SAMPLING	⊠Y□N □NA
b) NAME OF INDIVIDUAL PERFORMING SAMPLING	⊠Y□N □NA
c) ANALYTICAL METHODS AND TECHNIQUES.	⊠ Y □ N □ NA
d) RESULTS OF ANALYSES AND CALIBRATIONS.	⊠ Y □ N □ NA
e) DATES AND TIMES OF ANALYSES.	⊠ Y □ N □ NA
f) NAME OF PERSON(S) PERFORMING ANALYSES.	⊠ Y □ N □ NA
3. LABORATORY EQUIPMENT CALIBRATION AND MAINTENANCE RECORDS ADEQUATE.	\boxtimes S \square M \square U \square NA
4. PLANT RECORDS INCLUDE SCHEDULES, DATES OF EQUIPMENT MAINTENANCE AND REPAIR.	\boxtimes S \square M \square U \square NA
5. EFFLUENT LOADINGS CALCULATED USING DAILY EFFLUENT FLOW AND DAILY ANALYTICAL DATA.	⊠Y□N □NA
SECTION C - OPERATIONS AND MAINTENANCE	
TREATMENT FACILITY PROPERLY OPERATED AND MAINTAINED.	NA (FURTHER EXPLANATION ATTACHED <u>NO</u>)
1. TREATMENT UNITS PROPERLY OPERATED.	⊠S □M □U □NA
2. TREATMENT UNITS PROPERLY MAINTAINED.	⊠S□M□U□NA
3. STANDBY POWER OR OTHER EQUIVALENT PROVIDED.	\boxtimes S \square M \square U \square NA
4. ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE.	\boxtimes S \square M \square U \square NA
5. ALL NEEDED TREATMENT UNITS IN SERVICE	⊠S□M□U □NA
6. ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED. Facility employs 5 level IVs, 2 level III lab techs.	⊠S□M□U□NA
7. SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED.	\boxtimes S \square M \square U \square NA
8. OPERATION AND MAINTENANCE MANUAL AVAILABLE. STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED. PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED.	⊠ Y □ N □ NA ⊠ Y □ N □ NA ⊠Y □ N □ NA

RUIDOSO/RUIDOSO DOWNS WWTP	PERMIT NO. NM0029165						
SECTION C - OPERATIONS AND MAINTENANCE (CONT'D)							
9. HAVE BYPASSES/OVERFLOWS OCCURRED AT THE PLANT OR IN THE COLLECTION SYSTEM IN THE LAST YEAR? IF SO, HAS THE REGULATORY AGENCY BEEN NOTIFIED? HAS CORRECTIVE ACTION BEEN TAKEN TO PREVENT ADDITIONAL BYPASSES/OVERFLOWS?	□ Y ⊠ N □ NA □ Y □ N ⊠ NA □Y □ N ⊠ NA						
10.HAVE ANY HYDRAULIC OVERLOADS OCCURRED AT THE TREATMENT PLANT? IF SO, DID PERMIT VIOLATIONS OCCUR AS A RESULT?	□y⊠n □na □y□n ⊠na						
SECTION D - SELF-MONITORING							
PERMITTEE SELF-MONITORING MEETS PERMIT REQUIREMENTS. DETAILS:							
1. SAMPLES TAKEN AT SITE(S) SPECIFIED IN PERMIT.	⊠ y □ n □ na						
2. LOCATIONS ADEQUATE FOR REPRESENTATIVE SAMPLES.	⊠ y □ n □ na						
3. FLOW PROPORTIONED SAMPLES OBTAINED WHEN REQUIRED BY PERMIT.	⊠ y □ n □ na						
4. SAMPLING AND ANALYSES COMPLETED ON PARAMETERS SPECIFIED IN PERMIT.	⊠ y □ n □ na						
5. SAMPLING AND ANALYSES PERFORMED AT FREQUENCY SPECIFIED IN PERMIT.	⊠Y □ N □ NA						
6. SAMPLE COLLECTION PROCEDURES ADEQUATE	⊠ y □ n □ na						
a) SAMPLES REFRIGERATED DURING COMPOSITING.	⊠ y □ n □ na						
b) PROPER PRESERVATION TECHNIQUES USED.	⊠ y □ n □ na						
c) CONTAINERS AND SAMPLE HOLDING TIMES CONFORM TO 40 CFR 136.3.	⊠ y □ n □ na						
7. IF MONITORING AND ANALYSES ARE PERFORMED MORE OFTEN THAN REQUIRED BY PERMIT, ARE THE RESULTS REPORTED IN PERMITTEE'S SELF-MONITORING REPORT?	□Y□N⊠NA						
SECTION E - FLOW MEASUREMENT							
PERMITTEE FLOW MEASUREMENT MEETS PERMIT REQUIREMENTS. □ NA (FURTHER EXPLANATION ATTACHED NO) DETAILS:							
PRIMARY FLOW MEASUREMENT DEVICE PROPERLY INSTALLED AND MAINTAINED. TYPE OF DEVICE 12-inch Parshall flume	⊠y □ N □ NA						
2. FLOW MEASURED AT EACH OUTFALL AS REQUIRED.	⊠ y □ n □ na						
3. SECONDARY INSTRUMENTS (TOTALIZERS, RECORDERS, ETC.) PROPERLY OPERATED AND MAINTAINED.	⊠ y □ n □ na						
4. CALIBRATION FREQUENCY ADEQUATE RECORDS MAINTAINED OF CALIBRATION PROCEDURES. CALIBRATION CHECKS DONE TO ASSURE CONTINUED COMPLIANCE	$\boxtimes Y \square N \square NA$ $\boxtimes Y \square N \square NA$ $\boxtimes Y \square N \square NA$						
5. FLOW ENTERING DEVICE WELL DISTRIBUTED ACROSS THE CHANNEL AND FREE OF TURBULENCE.	⊠ Y □ N □ NA						
6. HEAD MEASURED AT PROPER LOCATION.	⊠ Y □ N □ NA						
7. FLOW MEASUREMENT EQUIPMENT ADEQUATE TO HANDLE EXPECTED RANGE OF FLOW RATES.	⊠ Y □ N □ NA						
SECTION F – LABORATORY							
PERMITTEE LABORATORY PROCEDURES MEET PERMIT REQUIREMENTS. □ S □ M □ U □ NA (FURTHER EXPLAIDETAILS:	NATION ATTACHED <u>YES</u>						

1. EPA APPROVED ANALYTICAL PROCEDURES USED (40 CFR 136.3 FOR LIQUIDS, 503.8(b) FOR SLUDGES) X Y N NA										
RUIDOSO/RUIDOSO	DOWNS WWTP					PERMIT NO. N	M0029165			
SECTION F - LABORATORY (CONT'D)										
2. IF ALTERNATIVE ANALYTICAL PROCEDURES ARE USED, PROPER APPROVAL HAS BEEN OBTAINED ⊠ Y □ N □ NA										
3. SATISFACTORY O	3. SATISFACTORY CALIBRATION AND MAINTENANCE OF INSTRUMENTS AND EQUIPMENT.									
4. QUALITY CONTR	OL PROCEDURES ADE	QUATE.				\boxtimes S \square M \square U \square	l na			
5. DUPLICATE SAM	4. QUALITY CONTROL PROCEDURES ADEQUATE. S □ M □ U □ NA 5. DUPLICATE SAMPLES ARE ANALYZED. 10 % OF THE TIME. □ Y □ N □ NA									
6. SPIKED SAMPLES	S ARE ANALYZED. <u>0</u>	% OF THE TIME.				⊠ y □ n □] _{NA}			
7. COMMERCIAL LA	ABORATORY USED.					⊠ y □ n □] na			
LAB NAME LAB ADDRESS PARAMETERS PER	LAB NAME Summit Laboratories Huther and Associates									
SECTION G - EFI	FLUENT/RECEIVIN	G WATERS OBSER	RVATIONS.	⊠s □м □ u □	NA (FURTHER EXPLAN	VATION ATTACHED NO).				
OUTFALL NO.	OIL SHEEN	GREASE	TURBIDITY	VISIBLE FOAM	FLOAT SOL.	(FURTHER EXPLANATION ATTACHED <u>NO</u>). LOAT SOL. COLOR				
001	NONE	NONE	NONE	NONE	NONE	CLEAR				
RECEIVING WATER	OBSERVATIONS <u>N</u>	<u>Ione</u>								
SECTION H - SLU	SECTION H - SLUDGE DISPOSAL									
SLUDGE DISPOSAL MEETS PERMIT REQUIREMENTS.										
1. SLUDGE MANAG	SEMENT ADEQUATE T	O MAINTAIN EFFLUE	NT QUALITY.			⊠s□м□	u 🗆 na			
2. SLUDGE RECORI	DS MAINTAINED AS R	EQUIRED BY 40 CFR 5	03.			⊠s □м □	u 🗆 na			
3. FOR LAND APPL	IED SLUDGE, TYPE OF	LAND APPLIED TO: _	CLASS A – GIVEN	AWAY (e.g., FORE	EST, AGRICULTURAL, I	PUBLIC CONTACT SIT	E)			
SECTION I - SAN	MPLING INSPECTION	ON PROCEDURES	(FURTHER EXPLANATIO	ON ATTACHED).						
1. SAMPLES OBTAI	NED THIS INSPECTION	1.				□y□n∣	× NA			
2. TYPE OF SAMPLE OBTAINED										
GRAB COMPOSITE SAMPLE METHOD FREQUENCY										
3. SAMPLES PRESE	3. SAMPLES PRESERVED. □ Y □ N ☒ NA									
4. FLOW PROPORTI	ONED SAMPLES OBTA	AINED.				□y□n∣	× NA			
5. SAMPLE OBTAIN	IED FROM FACILITY'S	SAMPLING DEVICE.				\square Y \square N	× NA			
6. SAMPLE REPRES	6. SAMPLE REPRESENTATIVE OF VOLUME AND MATURE OF DISCHARGE. ☐ Y ☐ N ☒ NA									
7. SAMPLE SPLIT WITH PERMITTEE.										

8. CHAIN-OF-CUSTODY PROCEDURES EMPLOYED.	□ y □ N ☒ NA
9. SAMPLES COLLECTED IN ACCORDANCE WITH PERMIT.	□ y □ n ⊠ na

Introduction

On July 22, 2013, Sarah Holcomb and Bruce Yurdin of the New Mexico Environment Department (NMED), Surface Water Quality Bureau (SWQB) conducted a Compliance Evaluation Inspection (CEI) at the Ruidoso/Ruidoso Downs Wastewater Treatment Plant (WWTP). The Ruidoso/Ruidoso Downs WWTP has a design flow capacity of 2.7 MGD (million gallons per day) and is classified as a major municipal discharger under the Federal Clean Water Act, Section 402, of the National Pollutant Discharge Elimination System (NPDES) permit program. It is assigned NPDES permit number NM0029165. This permit regulates the WWTP discharge to the Rio Ruidoso in Segment 20.6.4.209 of the Pecos River Basin according to the *State of New Mexico Standards for Interstate and Intrastate Surface Waters*, 20.6.4 NMAC. This segment includes the designated uses of domestic water supply, high quality coldwater aquatic life, irrigation, livestock watering, wildlife habitat, public water supply and primary contact.

The NMED performs a certain number of CEIs for the U.S. Environmental Protection Agency (USEPA), Region VI, under the NPDES permit program, in accordance with the Federal Clean Water Act. USEPA uses these inspections to determine compliance with the NPDES permit program. This inspection report is based on information provided by the permittee's representatives, observations made by the NMED inspector, and records and reports kept by the permittee and/or NMED.

Upon arrival at the WWTP at 1100 hours on July 22, 2013, the inspectors met Mr. Bobby Snowden, Department Supervisor, and Mr. Isaac Garcia, Chief Operator. Upon arrival, the inspector showed her credentials, explained the purpose of the inspection and conducted the entrance interview and went on a tour of the facility with Mr. Snowden and Mr. Garcia. Inspection of records and the laboratory commenced thereafter. An exit interview was conducted at 1500 hours on July 22, 2012 with Mr. Snowden and Mr. Garcia at the facility. The inspector did discuss the use of NetDMR with the facility representatives, and Mr. Snowden indicated that the use of NetDMR is on his agenda for the near future.

Treatment Scheme

The Ruidoso/Ruidoso Downs WWTP is a new facility that was placed online in April 2011. The remnants of the old plant still exist on the site, but have been blocked off; the old components that still make up part of the facility footprint but are not used are the influent screw pumps and the old equalization and aeration basins.

Influent enters the facility through a 24-inch line to the influent lift station. The influent lift station is equipped with four Flygt influent pumps, which are each capable of handling a 3 million gallon flow. There is a dedicated backup generator for the influent pumps. The flow travels from the influent pump station into the facility through a 12 inch Parshall flume and Magmaster flow meter. It is then conveyed to the coarse bar screen. The bar screen is a mechanical Ovivo bar screen with 0.25" openings. The bar screen is set on a float timer, but also has a regular timer for redundancy. The course screening facility is equipped with an emergency bypass. The screenings are sent to a hopper located next to the screen and materials are taken to the landfill.

After the coarse materials are removed from the influent, the flow enters a Smith & Loveless grit chamber. The grit is also sent to a hopper which is then taken to the landfill after drying. At this point, the operators have the capability to send flows that are over 1400 gpm to the equalization (EQ) basin. The current EQ basin consists of the old aeration basins from the old facility. The facility has 660,000 gallons of storage available to them here. If there is influent in the EQ basin, it is bled back into the plant prior to the grit/fines removal when the influent flow is less than 700 gpm.

After the grit chamber, the flow enters the fine screens. The screens are equipped with a 0.3mm opening. The screened material then goes through a rinsing process and is then sent to compactors and the grit classifier, while the filtrate continues through the rest of the plant. After this filtration process, the nitrogen is typically less than 3 mg/L, according to the facility's representatives.

The filtered influent then proceeds to biological treatment. This plant is designed as an intensive nutrient removal MBR (membrane bioreactor), and consequently, the wastewater is sent through a number of specialized chambers prior to entering the membranes. The first chamber the wastewater enters in this phase is an anaerobic selector, which functions specifically for bio-phosphorus removal. From this area, the wastewater then flows into a de-oxygenation basin, where it is then mixed with RAS (return activated sludge). From this point, the wastewater is then sent to the pre-anoxic zone. This particular basin is equipped with submersible mixers in order to keep the solids in suspension while maintaining anoxic conditions. Next is the pre-aeration basin, which is equipped with fine bubble diffusers to facilitate nitrogen stripping. Yet another anoxic zone (referred to as the post-anoxic zone) is the next step after the pre-aeration basin. At this point, facility operators have the option to add aluminum sulfate or methanol if needed to further reduce nitrogen and phosphorus levels in the wastewater. Solids from the post-anoxic basin are recycled back to the anaerobic basin to add food for the bio-phosphorus removal process. Currently, facility staff is relying on the biological methodology to remove as many nutrients as possible and are not adding chemicals.

At this point, the wastewater is sent to the MBR basins. There are three MBR trains, each capable of treating 900,000 gallons each. There is the capability to build the plant out to accommodate another train (capable of treating another 900,000 gallons) if the facility needs to do so in the future – there is an empty MBR basin at this time. Within each MBR basin, there are 8 lower and 8 upper cassettes. Each cassette contains 200 filters, which means there are approximately 3,200 filters in each basin (19,200 filters in total). These filters are equipped with a 10 year warranty. The MBR basins are where biological treatment as well as more filtration of the wastewater occurs.

From the MBR basins, the treated wastewater is conveyed to the UV disinfection facility. This facility is equipped with two UV banks, one of which is currently online. After disinfection, the effluent is pumped into the washwater wet well. Any effluent not pumped here then travels through an 18 inch Parshall flume and through an 18 inch line to the Rio Ruidoso.

Solids

WAS (waste activated sludge) is removed from the MBR and sent to the thickener. The thickener, with the assistance of a polymer, thickens the sludge to about 2.5-3%, and is then sent to the digester for stabilization. The digester contains 3 cells (and can be expanded to 4 cells if needed in the future). From the digester, sludge is sent to the belt filter press, and is then transferred outside to "cook" to meet the requirements of Class A sludge. The facility typically wastes 5 days a week and runs their filter press two days per week. When ready, the sludge is given away for beneficial use.

Further Explanations

Note: The sections are arranged according to the format of the enclosed EPA Inspection Checklist (Form 3560-3), rather than being ranked in order of importance.

Section F - Laboratory Evaluation - Overall Rating of "Satisfactory"

The permit states in Part III.C.5.a, Monitoring Procedures:

Monitoring must be conducted according to test procedures approved under 40 CFR Part 136, unless other test procedures have been specified in this permit or approved by the Regional Administrator.

40 CFR Part 136.3 states in Table I.B:

Parameter	Methodology58		Standard methods	ASTM	USGS/AOAC/Other					
9. Biochemical oxygen demand (BOD5), mg/L	Dissolved Oxygen Depletion		5210 B–2001		973.44 ³ , p. 17. ⁹ , I–1578–78, ⁸ See footnote. ^{10,63}					

And, Standard Methods 5210 B – 2001 states:

The DO update of seeded dilution water should be between 0.6 and 1.0 mg/L.

And,

Dilutions that result in a residual DO of at least 1 mg/L and a DO uptake of at least 2 mg/L after 5 d incubation produce the most reliable results.

Findings for Laboratory:

At the time of this inspection, it was very evident that the facility prides themselves on doing a consistent job keeping accurate data on the capabilities of their plant. The lab and procedures appeared to be well managed and well monitored.

The temperature of the BOD incubator discussed in the last inspection report appeared to have been resolved. The internal thermometer, when checked during this inspection, was reading in the required range.

During review of the BOD calculations themselves for January 2013, the inspector noted that one of the final BOD bottles had not qualified as required in Standard Methods, having resulted in a residual DO of less than 1.0 mg/L. This particular bottle was still used in the overall calculations for reporting on the DMR.

Discharge Monitoring Report Calculation Check

The DMR calculation check was conducted for the parameter of BOD for the months of January 2013. \checkmark = in agreement with calculation result submitted on facility's DMR.

<u>Date</u>	BOD Result
1-2-2013	0.94 mg/L
1-9-2013	1.05 mg/L
1-16-2013	1.46 mg/L
1-23-2013	1.12 mg/L
1-30-2013	1.05 mg/L

Loading:

January's 30-day average:

0.94 mg/L x 8.34 x 2.0 mgd = 15.68 lbs/day

1.05 mg/L x 8.34 x 1.5 mgd = 13.14 lbs/day

 $1.46 \text{ mg/L } \times 8.34 \times 1.39 \text{ mgd} = 16.93 \text{ lbs/day}$

1.12 mg/L x 8.34 x 1.4 mgd = 13.08 lbs/day

1.05 mg/L x 8.34 x 1.42 mgd = 12.43 lbs/day

Avg: (15.68+13.14+16.93+13.08+12.43)/5 = 14.25 lbs/day (This was reported as 14.2 lbs/day)

January's 7-day average = 16.93 lbs/day (This was reported as 16.9 lbs/day) ✓

Concentration:

January's 30-day average = (0.94 mg/L + 1.05 mg/L + 1.46 mg/L + 1.12 mg/L + 1.05 mg/L)/5 = 1.12 mg/L (this was reported as <2 mg/L) \checkmark

January's 7-day average = 1.46 mg/L (This was reported as <2 mg/L) ✓